PROCESSING COPY

CR

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

	Secs. 793 and 794, the transmission or rev	S-E-C-R-E-		
	<u> </u>			
DUNTRY	USSR (Primorskiy Kray)		REPORT	
JBJECT	Port Installations at Na	akhodka	DATE DISTR.	8 March 1957
			NO. PAGES	
			REQUIREMENT NO.	
ATE OF		ENCLO	REFERENCES	
ACE & ATE ACQ.		PLE	SE ROUTE	
	SOURCE EVALUATIONS ARE	DEFINITIVE. APPRA	ISAL OF CONTENT IS	TENTATIVE.
· A_	six-page report and two sl	cetches on port	installations at	Nakhodka
		4. 1		
		•	·	
l				
	-			
	``			
	4.1			
•	•			
	S			
		4		
		\$	•	
		•		
	9323. 1	S-E-C-R-E-T	!	
	The state of the s	1.164		25X1




			
	SECRET	1	
		pege 2	
			2
		isy in the northwesternmost	
cove of Bukhta Nakho	dka (See "A" of attached Sketched Alon	gside this quay are two	
small office building	gs, one the Maritima Office an	d the other the Personnel	
Office	Inside the Maritime re one may purchase, for Sovie	Office building is a	2
SHALL 165 DAM MID MID.			
		inmediately around	2
the corner of the qu	ay, was the Soviet motor-ship	ILYICH (See atteched	_`
Sketch No. 1). The	MAICH is a 6,400-ton (sic) ma	rchantman carrying	
both passengers and	cargo on a scheduled run betwe	en Nakhodka and Komehatka;	
	f call on Kamchatka are unknom		4
			7
	SECRET		_
			2


	SECRET	
	. pege 3	
	. "Q.ES J	25)
		,
	concerning the numbered areas on	
the	enclosed overlay (Sketch No. 1):	
a.	No submarines were observed within area (1), although two M-type	
	submorines were observed steming north-northeast from an	
	unknown point of departure	2
	The submarines kept a fixed interval; there were no signs of towing.	
	Visibility did not permit clear observation of what area (1) is used	
	for, although several (sic) frigates and coastal putrol craft were	
	observed anchored or tied up in the cove.	25
. ძ	the building	20
	marked (2). The building measured about 200 maters in longth, 20	
	meters in width, and stood two stories high. (See sketch No. 1)	
7	The building was of sheet steel and glass construction.	
		2
	minor repairs to enips and boots	
	are accomplished inside the building, which is a machine shop.	
C.	At area (3), there are	2
	two long buildings, similar to the one described above, at positions	
	E and F. A smaller building, whose characteristics were indistinci, is	
	situated at G. Buildings E, F, and G lie immediately inshore from the	
	SECRET	2

Sanitized Copy	Approved for Release	2010/03/18:	: CIA-RDP80T00246A0329003	370001-6

	pcge L	
	shipyerd shoreline, and behind (west of) two large drydocks, at	
	positions C and D, which are large enough to accommodate freighters	
	(sic). All berths visible in the shippard south of drydocks C and D	
	appeared to be taken by small merchant craft lying in for repairs.	
	area (3) is a	
	shipbuilding and ship repair yard.	
d.	There is no sign of dredging, filling, construction, wrecking, or	
	other visible activity or equipment in the cove at area (b).	
The	observed a total of 35 to 40 swinging cremes in the Nakhodka Harbor. y appeared, uniformly, to be of the type shown in Sketch No. 2.	
The		2
	y appeared, uniformly, to be of the type shown in Sketch No. 2.	2
වර්ග	a group of about 40 ill-clad, idle man and woman lounging	2
වර්ග	a group of about 40 ill-clad, idle man and woman lounging at the quayside From their inactivity, they ware	2
වර්ග	a group of about 40 ill-clad, idle man and woman lounging at the quayside From their inactivity, they ware	2
වර්ග	a group of about 40 ill-clad, idle man and woman lounging at the quayside From their inactivity, they ware	
වර්ග	a group of about 40 ill-clad, idle man and woman lounging at the quayside From their inactivity, they ware	
වර්ග	a group of about 40 ill-clad, idle man and woman lounging at the quayside From their inactivity, they ware	



Sketch no.2 Typical Crane at Nakhodka



SECRET

25X1

25X1

